

NASA Ames Research Center Drinking Water System

2024 Lead Service Line Inventory

October 29, 2024

Dear Ames Community,

As part of our commitment to maintaining a safe drinking water supply, we are updating you on the 2024 Lead Service Line Inventory. This inventory is part of our compliance with state and federal regulations for our drinking water system, including the most recent update completed October 15, 2024. Our Lead Service Line Inventory records all service lines, which are the pipes that connect your building's plumbing to the main water line, including dedicated fire lines. The goal is to ensure all service lines meet safety standards and do not contain lead, which can pose health risks over time if present.

It is important to clarify that all service lines within NASA Ames' water system have been confirmed as non-lead. These current material identifications are primarily based on visual inspections with support from construction records. Additionally, any service lines that are four (4) inches in diameter or larger, as well as service lines and buildings installed after January 1, 1986, are determined by the US Environmental Protection Agency and State of California to be free of lead. This determination is based on federal and state standards that have mandated the use of lead-free materials for service lines since 1986.

Facilities such as storage sheds, which do not have drinking water supplies or other water service lines, are not included in this inventory update. This Lead Service Line Inventory will be updated as new information and inspections become available.

If you have questions about your specific building or if you do not see your building listed in the inventory, please feel free to reach out. I am available to discuss and address any concerns you may have.

Sincerely,

Jeanne

Jeanne Sabin
Water Compliance Program Manager
Environmental Management Division
NASA Ames Research Center
M/S 204-15
Building N204, Room 102-11
Moffett Field, CA 94035-0001

Office: 650-604-1800

Mobile: 650-582-7321

Email: jeanne.m.sabin@nasa.gov

Pronouns: She, Hers

Detailed Inventory

Date Last Updated: October 16, 2024

Purpose of this worksheet: To provide a template for water systems to track materials for each service line in their distribution system.

General Instructions: Each row in this worksheet represents one service line connecting the water main to the customer's plumbing. The columns with the aqua shading are required for the Inventory Summary tab. Note that users can freeze panes to enable them to see the headings and notes when entering data. The worksheet includes example rows and is formatted for approximately 10,000 entries. Please refer to the red triangle in the upper corner for additional instructions.

Error Count: 0
Rows Missing Information: 0

Location Information			System-Owned Portion										Customer-Owned Portion						Enter Service Line Information (appears in error or missing columns as filed correctly, see instructions)			
Unique Service Line ID	Street Address	Other Locational Identifier	System-Owned Portion Service Line Material Classification	Lead Connector Present?	If Material Anything Other than "Lead" in Column C, Was Material Ever Previously Lead?	Service Line Installation Date	Service Line Size (Inches)	Basis of Material Classification	Was the Service Line Material Field Verified?	Describe the Field Verification Method	Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size (Inches)	Basis of Material Classification	Was the Service Line Material Field Verified?	Describe the Field Verification Method	Enter the Date of Field Verification	Notes	Material Classification of error or missing information appears in error or missing columns as filed correctly, see instructions	
8V-G1	G1	Bay View Campus	Non-Lead - Other	No	No	2019		Installation date is after state or local lead ban	No				Non-Lead - Other	2019		Installation date is after state or local lead ban	No				Non-lead	
8V-G2	G2	Bay View Campus	Non-Lead - Other	No	No	2019		Installation date is after state or local lead ban	No				Non-Lead - Other	2019		Installation date is after state or local lead ban	No				Non-lead	
8V-G3	G3	Bay View Campus	Non-Lead - Other	No	No	2019		Installation date is after state or local lead ban	No				Non-Lead - Other	2019		Installation date is after state or local lead ban	No				Non-lead	
8V-G4	G4	Bay View Campus	Non-Lead - Other	No	No	2019		Installation date is after state or local lead ban	No				Non-Lead - Other	2019		Installation date is after state or local lead ban	No				Non-lead	
MS02-1-Fire	MS02	Maffett Airfield Complex	Non-Lead - Other	No	No	1993	4.00	Service line diameter 4 inches or greater	No			Building is currently under renovation, with full replacement of service lines expected in 2024 and 2025.	Non-Lead - Other	1993	4.00	Service line diameter 4 inches or greater	No				Building is currently under renovation, with full replacement of service lines expected in 2024 and 2025.	Non-lead
MS02-2-Fire	MS02	Maffett Airfield Complex	Non-Lead - Other	No	No	1993	4.00	Service line diameter 4 inches or greater	No			Building is currently under renovation, with full replacement of service lines expected in 2024 and 2025.	Non-Lead - Other	1993	4.00	Service line diameter 4 inches or greater	No				Building is currently under renovation, with full replacement of service lines expected in 2024 and 2025.	Non-lead
MS02-1-Fire	MS02	Maffett Airfield Complex	Non-Lead - Other	No	No	1993	4.00	Service line diameter 4 inches or greater	No			Building is currently under renovation, with full replacement of service lines expected in 2024 and 2025.	Non-Lead - Other	1993	4.00	Service line diameter 4 inches or greater	No				Building is currently under renovation, with full replacement of service lines expected in 2024 and 2025.	Non-lead
MS02-1	MS02	Maffett Airfield Complex	Galvanized	No	No	1993	2.00	Field inspection	Yes	Other	10/4/2024	Visual inspection from ground near building edge. Service line is directly connected to an 8" cast iron main, therefore is not GRR.	Galvanized	1993	2.00	Field inspection	Yes	Other	10/4/2024	Visual inspection from ground near building edge. Service line is directly connected to an 8" cast iron main, therefore is not GRR.		Non-lead
MS02-2	MS02	Maffett Airfield Complex	Galvanized	No	No	1993	2.00	Field inspection	Yes	Other	10/4/2024	Visual inspection from ground near building edge. Service line is directly connected to an 8" cast iron main, therefore is not GRR.	Galvanized	1993	2.00	Field inspection	Yes	Other	10/4/2024	Visual inspection from ground near building edge. Service line is directly connected to an 8" cast iron main, therefore is not GRR.		Non-lead
MS02	MS02	Maffett Airfield Complex	Non-Lead - Other	No	No	1993	3.00	Field inspection	Yes	Visual inspection at the meter pit	10/4/2024	3" steel pipe. Verified by visual inspection.	Non-Lead - Other	1993	3.00	Field inspection	Yes	Visual inspection at the meter pit	10/4/2024	3" steel pipe. Verified by visual inspection.		Non-lead
MS02-1	MS02	Maffett Airfield Complex	Non-Lead - Copper	No	No	1992	2.00	Field inspection	Yes	Visual inspection at the meter pit	8/9/2024	Completed visual inspection and scratch test.	Non-Lead - Copper	1992	2.00	Field inspection	Yes	Visual inspection at the meter pit	8/9/2024	Completed visual inspection and scratch test.		Non-lead
MS02-2-Fire	MS02	Maffett Airfield Complex	Non-Lead - Other	No	No	1992	4.00	Service line diameter 4 inches or greater	No			Completed visual inspection of fire line in September 2024.	Non-Lead - Other	1992	4.00	Service line diameter 4 inches or greater	No				Completed visual inspection of fire line in September 2024.	Non-lead
MS02-1	MS02	Maffett Airfield Complex	Non-Lead - Other	No	No	2023	3.00	Installation date is after state or local lead ban	Yes	Other	1/11/2024	3" ductile iron. Service lines replaced from main to building in 2023.	Non-Lead - Other	2023	3.00	Installation date is after state or local lead ban	Yes	Other	1/11/2024	3" ductile iron. Service lines replaced from main to building in 2023.		Non-lead
MS02-2-Fire	MS02	Maffett Airfield Complex	Non-Lead - Other	No	No	2023	8.00	Service line diameter 4 inches or greater	No			Service line replaced from main to building in 2023.	Non-Lead - Other	2023	8.00	Service line diameter 4 inches or greater	No				Service line replaced from main to building in 2023.	Non-lead
MS03-1-Fire	MS03	Maffett Airfield Complex	Non-Lead - Other	No	No	1993	4.00	Service line diameter 4 inches or greater	No			Completed visual inspection of fire line in September 2024.	Non-Lead - Other	1993	4.00	Service line diameter 4 inches or greater	No				Completed visual inspection of fire line in September 2024.	Non-lead
MS04	MS04	Maffett Airfield Complex	Non-Lead - Other	No	No	1993	1.00	Field inspection	Yes	Visual	8/9/2024	1" ductile iron at entry into building, with scratch test. Verified as magnetic material in field test.	Non-Lead - Other	1993	1.00	Field inspection	Yes	Visual	8/9/2024	1" ductile iron at entry into building, with scratch test. Verified as magnetic material in field test.		Non-lead
MS05	MS05	Maffett Airfield Complex	Non-Lead - Other	No	No	1993	1.50	Field inspection	Yes	Other	10/4/2024	Steep pipe from ground, through bronze valve, to copper pipe entering building verified by visual inspection.	Non-Lead - Other	1993	1.50	Field inspection	Yes	Other	10/4/2024	Visual inspection of service line entering building. Service line is connected to a 7" steel line, connected to an 8" main, therefore is not GRR.		Non-lead
MS06-1	MS06	Maffett Airfield Complex	Galvanized	No	No	1993	2.00	Field inspection	Yes	Other	10/4/2024	Visual inspection of service line entering building. Service line is connected to an 8" steel line, connected to an 8" main, therefore is not GRR.	Galvanized	1993	2.00	Field inspection	Yes	Other	10/4/2024	Visual inspection of service line entering building. Service line is connected to a 7" steel line, connected to an 8" main, therefore is not GRR.		Non-lead
MS06-2-Fire	MS06	Maffett Airfield Complex	Non-Lead - Other	No	No	1993	6.00	Service line diameter 4 inches or greater	Yes	Other	10/4/2024	Completed visual inspection of fire line in October 2024.	Non-Lead - Other	1993	6.00	Service line diameter 4 inches or greater	Yes	Other	10/4/2024	Completed visual inspection of fire line in October 2024.		Non-lead
MS07	MS07	Maffett Airfield Complex	Non-Lead - Copper	No	No	1993	2.00	Field inspection	Yes	Other	10/4/2024	Completed visual inspection and scratch test.	Non-Lead - Copper	1993	2.00	Field inspection	Yes	Other	10/4/2024	Completed visual inspection and scratch test.		Non-lead
MS08	MS08	Maffett Airfield Complex	Non-Lead - Other	No	No	1990	6.00	Installation date is after state or local lead ban	No			Installation date is after state or local lead ban	Non-Lead - Other	1990	6.00	Installation date is after state or local lead ban	No				Installation date is after state or local lead ban	Non-lead
MS09-1	MS09	Maffett Airfield Complex	Non-Lead - Other	No	No	1993	3.00	Field inspection	Yes	Visual inspection at the meter pit	10/4/2024	Visual inspection at the meter pit	Non-Lead - Copper	1993	3.00	Field inspection	Yes	Visual inspection at the meter pit	10/4/2024	Visual inspection at the meter pit		Non-lead
MS09-2	MS09	Maffett Airfield Complex	Non-Lead - Copper	No	No	1993	4.00	Service line diameter 4 inches or greater	Yes	Visual inspection at the meter pit	10/4/2024	Visual inspection at the meter pit	Non-Lead - Copper	1993	4.00	Service line diameter 4 inches or greater	Yes	Visual inspection at the meter pit	10/4/2024	Visual inspection at the meter pit		Non-lead
MS09-3	MS09	Maffett Airfield Complex	Non-Lead - Copper	No	No	1993	2.00	Field inspection	Yes	Visual inspection at the meter pit	10/4/2024	Completed visual inspection and scratch test.	Non-Lead - Copper	1993	2.00	Field inspection	Yes	Visual inspection at the meter pit	10/4/2024	Completed visual inspection and scratch test.		Non-lead
MS09-4	MS09	Maffett Airfield Complex	Non-Lead - Copper	No	No	1993	4.00	Service line diameter 4 inches or greater	Yes	Visual inspection at the meter pit	10/4/2024	Completed visual inspection and scratch test.	Non-Lead - Copper	1993	4.00	Service line diameter 4 inches or greater	Yes	Visual inspection at the meter pit	10/4/2024	Completed visual inspection and scratch test.		Non-lead
MS00	MS00	Maffett Airfield Complex	Non-Lead - Other	No	No	1993	4.00	Service line diameter 4 inches or greater	No			Building is currently under renovation construction. Visual inspection and verification as magnetic material in field test completed September 2024.	Non-Lead - Other	1993	4.00	Service line diameter 4 inches or greater	No				Building is currently under renovation construction. Visual inspection and verification as magnetic material in field test completed September 2024.	Non-lead
MS03	MS03	Maffett Airfield Complex	Non-Lead - Copper	No	No	1993	3.00	Field inspection	Yes	Visual inspection at the meter pit	10/4/2024	Completed visual inspection and scratch test.	Non-Lead - Copper	1993	3.00	Field inspection	Yes	Visual inspection at the meter pit	10/4/2024	Completed visual inspection and scratch test.		Non-lead
MS04	MS04	Maffett Airfield Complex	Non-Lead - Other	No	No	1993	1.00	Field inspection	Yes	Visual	8/9/2024	1" ductile iron at entry into building, verified as magnetic material in field test.	Non-Lead - Other	1993	1.00	Field inspection	Yes	Visual	8/9/2024	1" ductile iron at entry into building, verified as magnetic material in field test.		Non-lead
MS05	MS05	Maffett Airfield Complex	Non-Lead - Other	No	No	1993		Field inspection	Yes	Visual	6/13/2017	2" ductile iron service line, connected to 30" PVC main. Visual inspections of vaults around building during 2017 Cross Connection Control Survey. Building is currently under renovation construction.	Non-Lead - Other	1993		Field inspection	Yes	Visual	6/13/2017	2" ductile iron service line, connected to 30" PVC main. Visual inspections of vaults around building during 2017 Cross Connection Control Survey. Building is currently under renovation construction.		Non-lead
MS06	MS06	Maffett Airfield Complex	Non-Lead - Copper	No	No	1993	2.00	Field inspection	Yes	Visual	10/4/2024	Completed visual inspection immediately at entry into building.	Non-Lead - Copper	1993	2.00	Field inspection	Yes	Visual	10/4/2024	Completed visual inspection immediately at entry into building.		Non-lead
MS09	MS09	Maffett Airfield Complex	Non-Lead - Other	No	No	1992	4.00	Service line diameter 4 inches or greater	No			Completed visual inspection in September 2024.	Non-Lead - Other	1992	4.00	Service line diameter 4 inches or greater	No				Completed visual inspection in September 2024.	Non-lead
MS04	MS04	Maffett Airfield Complex	Non-Lead - Copper	No	No	1994		Field inspection	Yes	Visual	10/4/2024	1" copper line connected to 8" main. Visual inspection and scratch test. Verified as magnetic material in field test.	Non-Lead - Copper	1994		Field inspection	Yes	Visual	10/4/2024	1" copper line connected to 8" main. Visual inspection and scratch test. Verified as magnetic material in field test.		Non-lead
MS05	MS05	Maffett Airfield Complex	Galvanized	No	No	1944	2.00	Field inspection	Yes	Other	10/4/2024	Visual inspection from ground near building edge. Service line is directly connected to an 8" main, therefore is not GRR.	Galvanized	1944	2.00	Field inspection	Yes	Other	10/4/2024	Visual inspection from ground near building edge. Service line is directly connected to an 8" main, therefore is not GRR.		Non-lead
MS05A	MS05A	Maffett Airfield Complex	Non-Lead - Other	No	No	1999		Installation date is after state or local lead ban	No			Installation date is after state or local lead ban	Non-Lead - Other	1999		Installation date is after state or local lead ban	No				Installation date is after state or local lead ban	Non-lead

M887	M887	CANG	Non-Lead - Other	No	No	1999		Installation date is after state or local lead ban	No			Non-Lead - Other	1999	Installation date is after state or local lead ban	No			Non-lead	
M780	M780	Majeff Airfield Complex	Non-Lead - Other	No	No	1999		Installation date is after state or local lead ban	No			Non-Lead - Other	1999	Installation date is after state or local lead ban	No			Non-lead	
M901	M901	Majeff Airfield Complex	Non-Lead - Copper	No	No	1987	1.25	Installation date is after state or local lead ban	Yes	Other	10/4/2024	Non-Lead - Copper	1987	1.25	Installation date is after state or local lead ban	Yes	Other	10/4/2024	Visual inspection of pipe near building at eyewash station
M934	M934	Majeff Airfield Complex	Galvanized	No	No	1940	3.00	Field inspection	Yes	Visual inspection at the meter pit	10/4/2024	Galvanized	1940	3.00	Field inspection	Yes	Visual inspection at the meter pit	10/4/2024	3" galvanized iron service connection into building is directly connected to an 8" main, therefore is not GIB.
M934A	M934A	Majeff Airfield Complex	Non-Lead - Copper	No	No	1996	2.00	Installation date is after state or local lead ban	Yes	Visual inspection at the meter pit	10/4/2024	Non-Lead - Copper	1996	2.00	Installation date is after state or local lead ban	Yes	Visual inspection at the meter pit	10/4/2024	
M944-1	M944	Majeff Airfield Complex	Non-Lead - Other	No	No	1941	1.00	Field inspection	Yes	Visual	10/4/2024	Non-Lead - Other	1941	1.00	Field inspection	Yes	Visual	10/4/2024	1" ductile iron. Completed visual inspection at above ground entry into building. Verified as magnetic material in field test. Expected to be demolished by 2025.
M944-2-Fire	M944	Majeff Airfield Complex	Non-Lead - Other	No	No	1941	4.00	Service line diameter 4 inches or greater	No			Non-Lead - Other	1941	4.00	Service line diameter 4 inches or greater	No			
N227-1-Fire	N227	Ames Campus	Non-Lead - Other	No	No	1950	6.00	Service line diameter 4 inches or greater	No		Completed visual inspection of fire line in September 2024.	Non-Lead - Other	1950	6.00	Service line diameter 4 inches or greater	No		Completed visual inspection of fire line in September 2024.	
N27C	N27C	Ames Campus	Non-Lead - Other	No	No	1999		Installation date is after state or local lead ban	No			Non-Lead - Other	1999	Installation date is after state or local lead ban	No				
N244	N244	Ames Campus	Non-Lead - Other	No	No	2024		Installation date is after state or local lead ban	No		Building is currently under renovation construction. All service lines are being removed and newly installed back to main.	Non-Lead - Other	2024	Installation date is after state or local lead ban	No			Building is currently under renovation construction. All service lines are being removed and newly installed back to main.	
N200	N200	Ames Campus	Non-Lead - Copper	No	No	1942	3.00	Field inspection	Yes	Visual inspection at the meter pit	10/4/2024	Non-Lead - Copper	1942	3.00	Field inspection	Yes	Visual inspection at the meter pit	10/4/2024	
N201	N201	Ames Campus	Non-Lead - Copper	No	No	1943	2.00	Field inspection	Yes	Visual inspection at the meter pit	10/4/2024	Non-Lead - Copper	1943	2.00	Field inspection	Yes	Visual inspection at the meter pit	10/4/2024	
N202-1	N202	Ames Campus	Non-Lead - Copper	No	No	1950	1.00	Field inspection	Yes	Visual inspection at the meter pit	9/4/2024	Non-Lead - Copper	1950	1.00	Field inspection	Yes	Visual inspection at the meter pit	9/4/2024	Completed visual inspection and scratch test.
N202-2-Fire	N202	Ames Campus	Non-Lead - Other	No	No	1950	4.00	Service line diameter 4 inches or greater	No		Completed visual inspection of fire line in September 2024.	Non-Lead - Other	1950	4.00	Service line diameter 4 inches or greater	No		Completed visual inspection of fire line in September 2024.	
N203A	N203A	Ames Campus	Non-Lead - Copper	No	No	1965	2.00	Field inspection	Yes	Other	10/4/2024	Non-Lead - Copper	1965	2.00	Field inspection	Yes	Other	10/4/2024	Completed visual inspection and scratch test at riser.
N203-1	N203	Ames Campus	Galvanized	No	No	1941	1.50	Field inspection	Yes	Visual	10/4/2024	Galvanized	1941	1.50	Field inspection	Yes	Visual	10/4/2024	Completed visual inspection and scratch test of riser entering building. Service line is directly connected to an 8" main, therefore is not GIB.
N203-2-Fire	N203	Ames Campus	Non-Lead - Other	No	No	1941	4.00	Service line diameter 4 inches or greater	No		Completed visual inspection in September 2024. Service line enters building above ground.	Non-Lead - Other	1941	4.00	Service line diameter 4 inches or greater	No		Completed visual inspection in September 2024. Service line enters building above ground.	
N204-1	N204	Ames Campus	Non-Lead - Copper	No	No	1952	1.50	Field inspection	Yes	Other	10/4/2024	Non-Lead - Copper	1952	1.50	Field inspection	Yes	Other	10/4/2024	Completed visual inspection and scratch test.
N204-2	N204	Ames Campus	Non-Lead - Copper	No	No	1952	3.00	Field inspection	Yes	Visual inspection at the meter pit	10/4/2024	Non-Lead - Copper	1952	3.00	Field inspection	Yes	Visual inspection at the meter pit	10/4/2024	Completed visual inspection and scratch test.
N204A	N204A	Ames Campus	Non-Lead - Other	No	No	1948	3.00	Field inspection	Yes	Other	10/2/2024	Non-Lead - Other	1948	3.00	Field inspection	Yes	Other	10/2/2024	3" ductile iron from visual inspection at water pit.
N205	N205	Ames Campus	Non-Lead - Copper	No	No	1965	1.00	Field inspection	Yes	Visual inspection at the meter pit	10/2/2024	Non-Lead - Copper	1965	1.00	Field inspection	Yes	Visual inspection at the meter pit	10/2/2024	
N206	N206	Ames Campus	Non-Lead - Copper	No	No	1945	4.00	Service line diameter 4 inches or greater	Yes	Visual	10/4/2024	Non-Lead - Copper	1945	4.00	Service line diameter 4 inches or greater	Yes	Visual	10/4/2024	
N206A-1	N206A	Ames Campus	Non-Lead - Other	No	No	1944	4.00	Service line diameter 4 inches or greater	No			Non-Lead - Other	1944	4.00	Service line diameter 4 inches or greater	No			
N206A-2	N206A	Ames Campus	Non-Lead - Other	No	No	1944	4.00	Service line diameter 4 inches or greater	No			Non-Lead - Other	1944	4.00	Service line diameter 4 inches or greater	No			
N206A-3	N206A	Ames Campus	Non-Lead - Other	No	No	1944	4.00	Service line diameter 4 inches or greater	No			Non-Lead - Other	1944	4.00	Service line diameter 4 inches or greater	No			
N206A-4	N206A	Ames Campus	Non-Lead - Other	No	No	1944	4.00	Service line diameter 4 inches or greater	No			Non-Lead - Other	1944	4.00	Service line diameter 4 inches or greater	No			
N207	N207	Ames Campus	Non-Lead - Copper	No	No	1944	2.00	Field inspection	Yes	Visual inspection at the meter pit	10/2/2024	Non-Lead - Copper	1944	2.00	Field inspection	Yes	Visual inspection at the meter pit	10/2/2024	Completed visual inspection and scratch test.
N207A	N207A	Ames Campus	Non-Lead - Copper	No	No	1973	2.00	Field inspection	Yes	Visual inspection at the meter pit	10/2/2024	Non-Lead - Copper	1973	2.00	Field inspection	Yes	Visual inspection at the meter pit	10/2/2024	Completed visual inspection and scratch test.
N210-1	N210	Ames Campus	Non-Lead - Copper	No	No	1939	2.50	Field inspection	Yes	Visual inspection at the meter pit	10/4/2024	Non-Lead - Copper	1939	2.50	Field inspection	Yes	Visual inspection at the meter pit	10/4/2024	Completed visual inspection and scratch test.
N210-2	N210	Ames Campus	Non-Lead - Copper	No	No	1939	1.25	Field inspection	Yes	Visual inspection at the meter pit	10/4/2024	Non-Lead - Copper	1939	1.25	Field inspection	Yes	Visual inspection at the meter pit	10/4/2024	Completed visual inspection and scratch test.
N211-1	N211	Ames Campus	Non-Lead - Copper	No	No	1943	3.00	Field inspection	Yes	Visual inspection at the meter pit	10/4/2024	Non-Lead - Copper	1943	3.00	Field inspection	Yes	Visual inspection at the meter pit	10/4/2024	Completed visual inspection and scratch test.
N211-2	N211	Ames Campus	Galvanized	No	No	1943	2.00	Field inspection	Yes	Visual inspection at the meter pit	10/4/2024	Galvanized	1943	2.00	Field inspection	Yes	Visual inspection at the meter pit	10/4/2024	Galvanized pipe from ground verified by visual inspection. Service line is directly connected to a 4" line, which is directly connected to a 10" main, therefore is not GIB.
N211-3	N211	Ames Campus	Non-Lead - Copper	No	No	1943	3.00	Field inspection	Yes	Visual inspection at the meter pit	10/4/2024	Non-Lead - Copper	1943	3.00	Field inspection	Yes	Visual inspection at the meter pit	10/4/2024	Completed visual inspection of Meter W210 in September 2024.
N211-4-Fire	N211	Ames Campus	Non-Lead - Other	No	No	1943	4.00	Service line diameter 4 inches or greater	No		Completed visual inspection of Meter W210 in September 2024.	Non-Lead - Other	1943	4.00	Service line diameter 4 inches or greater	No		Completed visual inspection of Meter W210 in September 2024.	
N211-5	N211	Ames Campus	Non-Lead - Other	No	No	1943	4.00	Service line diameter 4 inches or greater	No			Non-Lead - Other	1943	4.00	Service line diameter 4 inches or greater	No			
N211-6	N211	Ames Campus	Non-Lead - Other	No	No	1943	4.00	Service line diameter 4 inches or greater	No			Non-Lead - Other	1943	4.00	Service line diameter 4 inches or greater	No			
N211-7-Fire	N211	Ames Campus	Non-Lead - Other	No	No	1943	10.00	Service line diameter 4 inches or greater	No		Completed visual inspection of fire line in October 2024.	Non-Lead - Other	1943	10.00	Service line diameter 4 inches or greater	No		Completed visual inspection of fire line in October 2024.	
N212-1	N212	Ames Campus	Non-Lead - Copper	No	No	1950	3.00	Field inspection	Yes	Other	10/4/2024	Non-Lead - Copper	1950	3.00	Field inspection	Yes	Other	10/4/2024	Completed visual inspection and scratch test.
N212-2	N212	Ames Campus	Non-Lead - Copper	No	No	1950	2.00	Field inspection	Yes	Visual inspection at the meter pit	10/4/2024	Non-Lead - Copper	1950	2.00	Field inspection	Yes	Visual inspection at the meter pit	10/4/2024	Completed visual inspection in September 2024.
N213	N213	Ames Campus	Non-Lead - Other	No	No	2016		Installation date is after state or local lead ban	No			Non-Lead - Other	2016		Installation date is after state or local lead ban	No			
N215	N215	Ames Campus	Non-Lead - Copper	No	No	1940	2.00	Field inspection	Yes	Other	10/4/2024	Non-Lead - Copper	1940	2.00	Field inspection	Yes	Other	10/4/2024	Completed visual inspection and scratch test.
N216	N216	Ames Campus	Non-Lead - Other	No	No	1999		Installation date is after state or local lead ban	No			Non-Lead - Other	1999		Installation date is after state or local lead ban	No			
N216A	N216A	Ames Campus	Galvanized	No	No	1973	1.00	Field inspection	Yes	Visual inspection at the meter pit	8/29/2024	Galvanized	1973	1.00	Field inspection	Yes	Visual inspection at the meter pit	8/29/2024	1" wrapped galvanized. Service line is directly connected to an 8" main, therefore is not GIB.
N216B-1-Fire	N216B	Ames Campus	Non-Lead - Other	No	No	1973	4.00	Service line diameter 4 inches or greater	No		Completed visual inspection of fire line in September 2024.	Non-Lead - Other	1973	4.00	Service line diameter 4 inches or greater	No		Completed visual inspection of fire line in September 2024.	
N218A	N218A	Ames Campus	Non-Lead - Other	No	No	1984	1.00	Field inspection	Yes	Visual inspection at the meter pit	8/29/2024	Non-Lead - Other	1984	1.00	Field inspection	Yes	Visual inspection at the meter pit	8/29/2024	1" ductile iron. Completed visual inspection. Verified as magnetic material in field test.
N219-1	N219	Ames Campus	Non-Lead - Copper	No	No	1940	2.00	Field inspection	Yes	Visual inspection at the meter pit	9/20/2024	Non-Lead - Copper	1940	2.00	Field inspection	Yes	Visual inspection at the meter pit	9/20/2024	
N219-2-Fire	N219	Ames Campus	Non-Lead - Other	No	No	1940	6.00	Service line diameter 4 inches or greater	No		Completed visual inspection of fire line in September 2024.	Non-Lead - Other	1940	6.00	Service line diameter 4 inches or greater	No		Completed visual inspection of fire line in September 2024.	
N220	N220	Ames Campus	Non-Lead - Copper	No	No	1940	1.50	Field inspection	Yes	Other	10/4/2024	Non-Lead - Copper	1940	1.50	Field inspection	Yes	Other	10/4/2024	Completed visual inspection and scratch test.

